

# Part 573 Safety Recall Report

## 16V-565

**Manufacturer Name :** Cruiser RV

**Submission Date :** JUL 28, 2016

**NHTSA Recall No. :** 16V-565

**Manufacturer Recall No. :** NR



### Manufacturer Information :

**Manufacturer Name :** Cruiser RV

**Address :** 7805 North State Road 9  
PO Box 130 Howe IN 46746

**Company phone :** 866-277-5630

### Population :

**Number of potentially involved :** NR

**Estimated percentage with defect :** NR

### Vehicle Information :

**Vehicle 1 :** 2017-2017 Cruiser Shadow cruiser

**Vehicle Type :** TRAILERS

**Body Style :**

**Power Train :** NR

**Descriptive Information :** all floor plans

**Production Dates :** APR 21, 2016 - JUL 25, 2016

**VIN Range 1 : Begin :** NR

**End :** NR

☐ Not sequential

### Description of Defect :

**Description of the Defect :** The switched accessory LED light that is on the front cap of the camper may have a fault that could cause it to short and overheat. The investigation is ongoing.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** The light could overheat resulting in a fire.

**Description of the Cause :** The cause has not yet been determined

**Identification of Any Warning that can Occur :** We are unaware of any warning signs at this time investigation is still ongoing.

**Supplier Identification :****Component Manufacturer**

Name : Dehco Inc  
Address : 58263 Charlotte Ave  
Elkhart INDIANA 46517  
Country : United States

**Chronology :**

June 24, 2016 Heartland received information from a dealer claim concerning a fire that had occurred on the front cap at the LED light.  
On 7/18/16 one of our companies' Cruiser RV received information concerning a fire on the front cap with the same LED light. On 7/21 Heartland determined that there was a concern and agreed to proceed under the determination that this could be a safety concern and called the Vendor for meeting. The RV in question was returned to the factory for testing and on 7/28 a meeting with Dehco the Light supplier was held.

**Description of Remedy :**

Description of Remedy Program : The investigation is ongoing and no determination as to the cause or the remedy has been determined.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : as of 7/25/16 the light has been removed from production or the inventory has been held pending the determination and outcome of our investigation.

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported